

# PURCHASE REQUEST

Entity Name: \_\_\_\_\_

Fund Cluster: \_\_\_\_\_

Office/Section: <b>DSWD</b>		PR No.: <b>2020-10-1860</b>	Date: <b>10/21/2020</b>		
		Responsibility Center Code: _____			
Stock/ Property No.	Unit	Item Description	Quantity	Unit Cost	Total Cost
	job	<b>LABOR</b> Replace Steering Rack and Pinion Replace Power Steering Pump		3,500.00 3,500.00	3,500.00 3,500.00
		<b>PARTS</b> Steering Rack Assembly Power Steering Pump Power Steering Fluid		130,000.00 48,985.00 600.00	130,000.00 48,985.00 600.00
<b>***NOTHING FOLLOWS***</b>					
<div style="border: 1px solid black; padding: 5px; display: inline-block;">                 FINANCE MANAGEMENT DIVISION  <b>FUNDS AVAILABLE</b>                  BUDGET SECTION: <u>                    </u>                  DATE: <u>10/23/2020</u>                  REF: 710100300001000 (PL-N0000) Current                  01-2020-VI-21 (LWP) 3/6/20                  50293060-09 Comp. 3             </div>					
				<b>TOTAL</b>	<b>186,585.00</b>

DSWD FIELD OFFICE VI  
 9405 A MALABON CORRIDOR  
 2020-11-0990  
 RECEIVED BY: \_\_\_\_\_

ADARTEVICARIO G. GREGIO  
 REGIONAL DIRECTOR

**Purpose:** *Preventive Maintenance of 1 unit DMAX with Plate No. CJ4258.*

**Requested by:**

**Approved by:**

**Signature:** \_\_\_\_\_

**Printed Name:** ASUNCION M. SANTIAGO

**Designation:** OIC Chief- Promotive Division

[Signature]

MA. EVELYN B. MACAPOBRE, CESO III  
Regional Director

3. Estimated days of repairs are based on regular working days subject to factors beyond the control of the dealership.
4. It is understood that ISUZU ILOILO CORPORATION assumes no responsibility for the loss or damage by theft or fire to vehicle placed with them for storage, sale or repair.
5. This estimate is not valid as court evidence.

VAT \_\_\_\_\_  
Grand Total 186,585.00

INSPECTED BY: \_\_\_\_\_

CONFORME: \_\_\_\_\_

PRINTED NAME & SIGNATURE OF CUSTOMER / INSURANCE COORDINATOR

DSWD

Service Advisor

KENNETH J. MASANA

Service Manager

GILBERT G. TINOY